


PROJECT PHOTOS



Interior of dirty laundry room (04/13/2021)



Mezzanine slab edge supports installed (04/13/2021)



Overview of building from northwest (04/13/2021)






MEP rough-ins on east side (04/13/2021)





Installation of shower stalls (04/13/2021)



MEP rough-ins in gear room (04/13/2021)


	
Overview of building from southwest (04/15/2021)	Masonry façade construction on south face (04/15/2021)
	
Western mezzanine slab reinforcing installation (04/15/2021)	Reinforcing at dirty laundry room roof (04/15/2021)
	
Underside of shoring at western mezzanine (04/15/2021)	Placement of concrete at western mezzanine (04/20/2021)

	
Western mezzanine slab (04/20/2021)	Concrete placed at dirty laundry room roof (04/20/2021)
	
Overview of building south face (04/20/2021)	Mechanical room with mechanical pads (04/20/2021)
	
Electrical rough-ins (04/20/2021)	Typical drip edge and rafl installed at south face (04/20/2021)


	
Excavation of infiltration system #1 (04/21/2021)	Masonry façade on north side of apparatus bay (04/21/2021)
	
Overview of east side of apparatus bay (04/21/2021)	MEP rough-ins on east side (04/21/2021)
	
Masonry façade on south face and transition roof (04/21/2021)	Mock-up (04/23/2021)



Overview of building from southwest (04/23/2021)



Typical grouted beam pockets at CMU wall (04/23/2021)




MEP rough-ins on east side (04/23/2021)





Overview of western mezzanine roof (04/23/2021)




Overview of apparatus bay roof (04/23/2021)



Overview of western mezzanine (04/23/2021)

	
Overview of building from southeast (04/29/2021)	Overview of western mezzanine (04/29/2021)
	
Electrical rough-ins above dirty laundry room (04/29/2021)	West side of building (04/29/2021)
	
Overview of excavation for infiltration system #1 (04/29/2021)	Overview of OCS#1 outlet pipe (04/29/2021)

	
<p>Realigned electrical conduits for emergency power and telecom lines and compacted graded apparatus bay subgrade (04/29/2021)</p>	<p>North side of building (04/29/2021)</p>
	
<p>Mechanical room (04/29/2021)</p>	<p>MEP rough-ins on east side (04/29/2021)</p>
	
<p>Installation of stormwater infiltration system 2 (05/07/2021)</p>	<p>Installation of masonry façade on south side (05/07/2021)</p>



**Installation of apparatus bay trench drains
(05/12/2021)**



Overview of site from southwest (05/13/2021)



Overview of site from southeast (05/13/2021)



Overview of mechanical room (05/17/2021)





**Installation of stormwater infiltration system 1
(05/17/2021)**






Overview of apparatus bay (05/17/2021)

Town of Acton, MA
North Acton Fire Station

	
Installation of MEP pipe and duct insulation on east side (05/17/2021)	Start of retaining wall construction (05/17/2021)
	
Vapor barrier and rigid insulation installation of apparatus bay (05/19/2021)	Roof hatch and ladder on east side of building (05/19/2021)
	
Installation of staircase (05/19/2021)	Construction of retaining wall (05/21/2021)

	
Rooftop units installed on east side. Connections to be made to units. (05/21/2021)	Installation of apparatus bay radiant heating and slab reinforcement (05/21/2021)
	
Installation of WQU 1 (05/24/2021)	Construction of retaining wall (05/24/2021)
	
Backfilled stormwater infiltration system 1 (05/24/2021)	Apparatus bay immediately prior to concrete pour (05/25/2021)

	
Apparatus bay slab prior to finishing (05/25/2021)	Apparatus bay slab (05/27/2021)
	
Staircase with concrete placed (05/27/2021)	Partial installation of electrical panels on mezzanine (05/27/2021)
	
Overview of mezzanine (05/27/2021)	GSI tanks to be installed (05/27/2021)

	
<p>Start of below ceiling drywall in bunk areas (05/27/2021)</p>	<p>MEP in fitness room (05/27/2021)</p>
	
<p>Mechanical room (05/27/2021)</p>	<p>Windows installed on bunk room sides (05/27/2021)</p>
	
<p>Pavement subgrade preparation on west side of existing garage (05/27/2021)</p>	<p>Overview of building from southeast (05/28/2021)</p>



Windows installed on bunk room side (05/28/2021)




Installation of area and roof drains on north side (05/28/2021)



Installation of lights on west side (05/28/2021)



Typical radiant heating manifold. Pump to be installed. (05/28/2021)



Hallway between bunk rooms and showers (05/28/2021)



Overview of apparatus bay from mezzanine (05/28/2021)

	
Removal of rock mass at CB 2 (05/28/2021)	Retaining wall installed (05/28/2021)
	
Installation of mezzanine railing (05/28/2021)	MEP rough-ins outside of conference room (05/28/2021)