



Overview of building from southeast



Overview of building from northwest



Overview of building from northeast



Overview of building from southwest



GSI tank backfilling



Atane onsite performing test soils



Vent has been installed



Vent installation



Ceiling Painting



More Ceiling Painting



Complete Nichiha siding of the west side of building



Nichiha siding of the east side of building




Eversource deliver the transformer



Transformer has been installed



Installing front door glass



Front door glass has been installed