

**PROJECT PHOTOS**



**Underground plumbing installed (11/13/2020)**



**Installation of underground electrical conduits  
(11/18/2020)**



**Installation of water main on north side of building  
(11/20/2020)**



**Installed interior foundations (11/24/2020)**



**Backfilling of interior to slab subgrade (11/30/2020)**



**Installation of vapor barrier (12/01/2020)**

**PROJECT PHOTOS**



**Installation of floor drains (12/02/2020)**

**Installation of the 14-inch slab in decon/laundry room (12/02/2020)**



**Installation of radiant heating in slab west of apparatus bay (12/03/2020)**

**Installed hydrant on west side of building (12/03/2020)**



**Overview of building from southeast corner (12/03/2020)**

**Excavation for detention basin on north side of site (12/04/2020)**

**PROJECT PHOTOS**



**Slab on grade installed on east side of site  
(12/04/2020)**

**Slab on grade installed on west side of site (12/04/2020)**