



Overview of building from southeast



Overview of building from northwest



Overview of building from northeast



Overview of building from southwest



Setting up red cable box



Decorative steel bracket installation




Well drilling



More well drilling




Wall painting ongoing



Ceramic tile installation in bathroom



Down spouts installed around the building



Miscellaneous painting